

Loss Bulletin

Vero Equipment Breakdown Insurance



Committed to your success

No winners at these pokies

Loss details

Nature of business

RSL Club

Type of equipment

Pokies x 19, and
Electrical equipment

Age of equipment

1 year old

Forced to cease operating due to the COVID restrictions, this RSL club was closed down for over two months.

In preparing for the shutdown, the club turned off the power to their equipment, and moved pokies and associated equipment from their alfresco area to a dry, secure area inside the club. When all the equipment was secured and powered down, they turned off the lights and locked up the club.

Nine weeks later they returned to open up the club. After returning the pokies to the alfresco area, they powered up all their equipment and turned it back on. Unfortunately, 19 of the Pokies throughout the club could not restart and were found to be non-operational due to various component failures including mainboards, LCD button panels, power supplies, ticket printers, etc.

In addition, it was discovered that some of the lighting circuits and associated wiring and control system equipment was damaged and required replacement.



Final loss

\$32,000

How can I find out more?
Contact your broker or visit
vero.com.au